Sub: - Additional points to be incorporated in Quantity Audit by internal quality audit team.

In continuation to the quantity audit checklist following additional points are to be followed:

- 1. EE (QC) shall check actual measurements (atleast 5% of values of work done) at site for the work done with respect to that recorded in MB.
- 2. Also actual measurements for work done are to be cross-checked with design & drawing issued for execution purpose.

(K.W. Barapatre) SE(OC) Emp No. 32562

To, EE (QC)

CE(NM) ----- For information Pls.

SE(HQ) ----- For information Pls.

Email sent

PI. TOK Pyr AEEC RRD)