CIDCO/SE (HQ)/2015/235

Date: 18/02/2015
24/02/2015

## **CIRCULAR**

Sub: - Speed breakers, that are being provided to dissuade drivers from speeding their vehicles.

Ref: - A letter from Deputy Commissioner of Police (Traffic) under ref. no. **PO UP**AA/Wah / NM/2980/14, dtd 27/09/2014 received on 13/02/2015.

Dy. Commissioner of Police vide above referred letter inform that the complaint has been received by them regarding height and size of the speed breakers which are provided on the road, which differ and many are made without conforming to any specifications. These speed breakers are not provided as per the norms as specified by the Indian Road Congress (IRC) which specifies the size & height etc. of the speed breakers in the code no. IRC:99–1988. These badly designed speed breakers could lead to musculoskeletal disorders to drivers, particularly of two wheelers and the same create hazardous conditions on the road rather than act as a tool to prevent accidents.

In view of above, all the Superintending Engineers / Executive Engineers are requested to conduct the survey within their jurisdiction and remove the speed breaker that are not necessary and rectify the other speed breakers as per the norms specified in IRC. Approval from T&C is mandatory for locations of speed breakers for existing and as well as proposed.

This circular is issued as approved by CE (NM).

Encl: a/a.

SE (HQ)

To,

All the SE

All the EE

C.C. to:CE (MM)/CE(NMIA)/CE(SP)/Chief G.M (T&A): For information please.