

CIRCULAR

Sub : Compliance of Hon'ble High Court Order (PIL-71/2013) regarding repairs to pot holes in roads/streets including footways/footpath within Corporation jurisdiction.

Ref : 1. Circular issued by SE(HQ), No CIDCO/CBD/SE(HQ)/347 Dt.31.08.2015


2. Circular issued by SE(HQ), No CIDCO/SE(HQ)/CIR/EE(NM)/2022/01/87976 Dt.06.01.2022

With reference to above subject, necessary instructions regarding compliance orders of Hon'ble High Court Mumbai were already issued, vide above circular No.1

Vide above Circular No.02, it was informed to submit quarterly status report within 7 (seven) days of quarter ending so that same can be submitted to Urban Development Dept. Govt. of Maharashtra. However delay is observed for submission of Quarterly Status report within specified time from Nodal offices. Also status report does not include colour photographs of work execution.

This is once again being brought to notice that, all SEs/ EEs shall submit quarterly status report within 7 (Seven) days of quarter ending without fail. The status report shall include colour photographs, photographs showing display boards mentioning name, address, contract details of agency, extent of digging work permitted, safety sign boards, arrangements of warning provisions / lights put on streets at the place or around manhole near trench for knowledge of pedestrians.

This circular is issued as per approval of CE(NM).


(D. A. Wankhade)
Superintending Engineer (HQ)
Emp. No. 23141

Separately to:

All SEs ()

All EEs (NM)

CC : ACE(I) / ACE(II)/ ACE(III)/ACE(IV) : for information please.

CE(NM)/ CE(NMIA)/ CE(SP)/CE(NT) : for information please.